DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Procedure Qualification Record (PQR) Test

Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 01.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-000175 Address: 333 Burma Road **Date Inspected:** 17-May-2007

City: Oakland, CA 94607

34-0006

OSM Arrival Time: 630 **Project Name:** SAS Superstructure **OSM Departure Time:** 1700 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: American Bridge/Fluor Enterprises, a JV **Location:** Benicia, CA

CWI Name: Michael Johnson **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:**

Delayed / Cancelled: Yes No N/A

Component:

Summary of Items Observed:

Bridge No:

Caltrans Quality Assurance (QA) Inspector Mary Madere is present at the Ironworkers Apprenticeship Training Facility as requested by ABF for the continuing purpose of witnessing Procedure Qualification Record tests. On this date, the QA Inspector observed the following personnel present: Smith-Emery Company's Quality Control (QC) Representative Certified Welding Inspector (CWI) Mr. Michael Johnson, ABF Representatives Mr. Tommy Gibson and Mr. Rick Clayborn, Bay Arc Representative Mr. Rich Deveau and welder Mr. Dan Gordon.

The QA Inspector witnessed the completion of the fourth attempt of a maximum heat input Procedure Qualification Record (PQR) Test identified as ABF-PQR-014-1. This PQR test is being attempted using the flux-cored arc welding (FCAW-G) process with gas shielding and a mechanical device that travels on a magnetic track. Welder Mr. Dan Gordon deposited two weld passes on this date. For specific welding parameters recorded during this PQR and digital photographs that support these observations, see Caltrans Welding Witness Report, TL-6032 generated on this date.

The QA Inspector observed Davis Laboratories, Incorporated Radiographer Mr. Rich Lorenzo and his assistant Mr. Chris Davidson as they performed radiography on three PQR test plates identified as ABF-PQR-014-1, ABF-PQR-016-1 and ABF-PQR-016-2. See Mr. James Cochran's Caltrans Welding Witness Report, TL-6032, generated on this date for information regarding the radiography of the identified PQR test plates.

Summary of Conversations:

Davis Laboratories, Incorporated Radiographer Mr. Rich Lorenzo informed the QA Inspector that all three of the PQR test plates have passed radiographic testing. In addition, Mr. Lorenzo stated that he would have to leave the jobsite by 1400 hours on this date.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

Inspected By:	Madere, Mary	Quality Assurance Inspector
Reviewed By:	Cuellar,Robert	QA Reviewer